

02 -  
SVØ1

HONEYWELL EXCEL 100 STYRIVÉL

AI-7 COM








AI-8 COM

AI-9 COM

AI-10 COM





AI-11 COM

AI-12 COM



X2 1 11

X2 1 11



2NH22

2NR1

3NH1

3NH2/3NR1

INNBLÁSTURSHITI  
2H SUÐUR

RAKI 2H Í UTSÖGI

INNBLÁSTURHITANEMI  
KFRFIJ3 KJALLARI

HITASTIG KJALLARA RAKI KJALLARA  
Í UTSÖGI



HITASTYRING HF

ÞVERHOI TI 15A SIMAR 623366 - 29525  
TELEFAX 354-791 624966

SAFNAHUS VE

DAGS	HANNAD	YFIR	SAMI
1/02.97	Sigurður Sigurðsson		

UTGÁA	BLAD	30
	NÆSTA BLAD	31
	TEIKNING NR	